


AS SEEN FROM REAR



NOTES:-

1. ALL WIRING TO BE 22 SWG UNLESS OTHERWISE SPECIFIED
2. (a) AT UAX NO 12 & 13 PROVIDE CONNECTION TO SHELF JACK POINT U9 AS SHOWN THUS — 1 — 1 —
- (b) AT UAX NO 14 STRAP SHELF JACK POINT U9 TO U6 AS SHOWN THUS — 2 — 2 —
3. AT UAXS EMPLOYING COIN AND FEE CHECKING EQUIPMENTS STRAP SHELF JACK POINT U9 TO U10 AS SHOWN THUS — 3 — 3 —
4. PRIOR TO ISSUE 2 COLOUR OF BATT WIRING WAS BK
5. SHELF JACK U POINTS 1-3 AND 2-4 MAKE CONTACT WHEN RECEIVER WB700A IS JACKED OUT.

MANUFACTURER'S LINEN.

RI ADDED U1-4 MODIFIED		SHELF JACK WIRING CONNEXIONS FOR RECEIVER CARRIER	
FOR LOCAL AMENDMENT NO 14 PMS (1967) (U.S.)		WB NO 700A	
		UAX NO 12, 13 & 14	
AMENDMENT PARTICULARS		REC DATE	APP REF T40090
GPO APPROVED AS STANDARD		EXP/ADWW/1968	50V S
DRAWN / CHECKED		WIRING CIRCUIT	ATU 600900.
EDL			